Plugging of Drilled Wells Chapter 76.1004

Original Ground Level

Remove all removable casing.

Pressure Cement well from bottom to surface.

* Alternative Method
Bentonite grout (10 lb.
Per gallon or more with a
marsh funnel viscosity of
50 sec. Or equiv.)
Followed by a cemant plug
from land surface to a
depth of not less that 2 ft.

